Simulator Debugger for H8SX, H8S, and H8 Families V.5.09.00 Upgrade

Issue Date : 2010/6/7

Description

Simulator Debugger for H8SX, H8S, and H8 families has been upgraded to V.5.09.00.
Contents of the revision can be checked in the Tool News.
Additionally, you can get detailed information on the product on this product site.

Notes

- If the High-performance Embedded Workshop V.4.07.00 or later has not already been installed in your PC, the simulator debugger for H8SX, H8S, and H8 families cannot be updated to V.5.09.00. So be sure to update your High-performance Embedded Workshop to V.4.07.00 at first. For details of the High-performance Embedded Workshop V.4.07.00, see Tool News.

The URLs in the document may be subject to change or become invalid without prior notice. If you have any questions or concerns, please contact us here.