

Arroyo Update for 6300 and 4200-DR

The Arroyo Update program is used to upgrade your **6300 Series ComboSource** or **4200-DR Series Laser Diode Driver** to the latest version of firmware. Updates are released to add features, fix bugs, and otherwise improve the operation of the instrument.

The current firmware version is 2.22

If you are already running the current version of firmware, there is no need to run the update program. The firmware version can easily be found as it is displayed on power-up.

To upgrade your instrument, you will need to have the instrument connected via USB and the [USB drivers \(/wp-content/uploads/2021/04/ArroyoUSBDrivers.zip\)](/wp-content/uploads/2021/04/ArroyoUSBDrivers.zip) loaded.

The download link below is a ZIP file that contains the update program. No installation is required, and the update program will run right out of the ZIP file.

[Click Here to Download the Update Program \(/wp-content/uploads/2024/03/ArroyoUpdate-x300-v2.22-B254.zip\)](/wp-content/uploads/2024/03/ArroyoUpdate-x300-v2.22-B254.zip)