









## Mutilevel Metallization

- Adding more levels of metal
  - Each layer adds cost
    More layers allow for
  - smaller chip area
  - More transistors need more metal layers

© Chris Mack, 2013

 State-of-the-art today is 10 metal layers





